



PLASTISOL ADDITIVE

- BEAD ADHESIVE** 86 MESH OR LOWER RECOMEND NEED TO PUT DOWN HEAVY DEPOSIT AND SPRINGLE VINYL BEADS ON TOP THEN GO TO DRYER.
- CLEAR BASE** RECOMEND FOR MIXING GLITTER ,FINE METAL FLAKE SUCH AS SILVER,GOLD,COPPER,BRONZE AND ECT.FOR PRINTING GLITTER MAX SIZE .008X.008 SCREEN MESH 25 RECOMEND.
- EXTENDER BASE** PRINTERS USE FOR MANY APPICATIONS SUCH AS EXT INKS TO LOW THE COST OF COLORS INKS ON LT.GARMENT,UNDER BASE FOR SMOOT FINISHING PRINT,ADD PIGMENT SMALL % FOR LT.GARMENT PRINTS.
- FOAM BASE** FINISH PRINT LOOK LIKE FOAM 10-20%OF REGULAR COLORS CAN BE ADD COLOR WILL STAY THE SAME REQUIRED HIGHER TEMPARATURES TO CURE AND FOAM UP APROXIMATE 400F GARMENT TEMP. APROX 1-1.5 MINUTES.
- GLITTER BASE** USE FOR SPRINGLE GLITTER ON TOP 86 MESH HEAVY DEPOSIT RECOMEND FOR MAX ADHESION
- GG BASE** SAME APPICATION AS GLITTER BASE BUT GIVE SOFTER HAND WORK WELL WITH LARGER SIZE GLITTER.
- HD CLEAR** HIGH DENSITY CLEAR USE FOR PRINT ON TOP OF COLORS TO GET GLOSS LOOK OR TO GET RAISE EFFECT BY USING CAP FILM OR COAT SCREEN SEVERAL TIME PIGMENT& REG INKS CAN BE ADD TO BECOME REGULAR PRINTING INKS
- HD MIX BASE** WORK THE SAME WAY AS HD CLEAR EXCEPT NOT CLEAR FOR PRINTING COLORS RAISE EFFECT IT CLEAR SCREEN VERY WELL 70-80 MESH RECOMEND.
- MS BASE** STICKLY FOR PIGMENTS SYSTEM 10-20%CANBE ADD
- MSF BASE** SAME AS MS BASE EXCEPT IT YIELD FLAT LOOK INSTEAD GROSSLY LOOK.
- PUFF BASE** MOST PRINTER USE FOR EXTEND PUFF OR ADDITIVE BY PUTING 10-20% IN REGULAR INKS THEN PRINT ON DARK GARMENTS IMPROVE OPACITY ECONOMY WAY WITH OUT UNDER BASE WITH WHITE.
- REDUCER** IS OILY LIQUID USE FOR MAKING INKS THINER MORE WATERLY FOR FAST PRINTING .WARNING DO NOT USE TOO MUCH OTHERWISE INKS WILL NOT CURE AND STAY TACKY AND WASH OFF. 1-7% RECOMEND.
- SOFTHAND CLEAR** ADDTIVE CAN BE ADD TO ANY INKS TO GET SOFT FEEL HELP PENETRATE IN TO FABRIC. SOFTHAND CLEAR CAN USE BY ITSELF BUY ADD 5% PIGMENT OR INKS PRINT WITH 280-300 MESH YOU GET SUPERSOFT LIKE WATERBASE.
- TOP COAT** DESIGN FOR HEAT TRANFER BY PRINT TOPCOAT ON REGULAR PAPER AS A MASK 200-280 MESH RECOMEND THEN PRINT COLOR ONE COLOR AT A TIME GEL EACH COLOR THEN HEAT TRANFER FOR BETTER ADHESION PRINT FOIL ADHESIVE LAST OR PUT WHITE INKS 20-30%INTO FOIL ADHESIVE FOR DARK GARMENT.
- ATTENTION** ALL PLASTISOL INKS SHOULD BE CURE AT 325 F GARMENT TEMPARATURE FOR AT LEAST 1 MINUTE OR MORE DEPEND ON TYPE OF GARMENT AND HOW MANY YOU PUT IN DRYER AT ONE TIME.